

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicants : H. FUKSHIMA, et al.

**Certificate of Correction Branch**

Patent No. : 7,709,282

Issued: May 4, 2010

Appln. No. : 10/575,489

Filed: April 12, 2006

For : A METHOD FOR PRODUCING A LIGHT-EMITTING DEVICE

**REQUEST FOR CERTIFICATE OF CORRECTION**

Commissioner for Patents  
U.S. Patent and Trademark Office  
Customer Service Window, Mail Stop Certificate of Correction Branch  
Randolph Building  
401 Dulany Street  
Alexandria, VA 22314

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following errors appearing in the printed patent, which are apparently the fault of the U.S. Patent and Trademark Office. Thus, no fee is required to be paid to correct this error.

At column 16, lines 64-65 (claim 1, lines 8-9) of the printed patent, "wherein said transfer layer" should read --wherein a thickness of said transfer layer--. This change was made on page 2, line 9 of the Examiner's Amendment in the Notice of Allowance mailed December 4, 2009.

At column 17, line 5 (claim 1, line 16) of the printed patent, "wherein a pitch" should read -- wherein a pitch of said minute unevenness structure--. This change was made on page 2, line 11 of the Examiner's Amendment in the Notice of Allowance mailed December 4, 2009.


Therefore, it is respectfully requested that a Certificate of Correction issue in the above-identified patent as follows:

At column 16, lines 64-65 (claim 1, lines 8-9) of the printed patent, "wherein said transfer layer" should read --wherein a thickness of said transfer layer--.

At column 17, line 5 (claim 1, line 16) of the printed patent, "wherein a pitch" should read -- wherein a pitch of said minute unevenness structure--.

Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted,  
H. FUKSHIMA, et al.

  
\_\_\_\_\_  
Bruce H. Bernstein  
Reg. No. 29,027

November 4, 2010  
GREENBLUM & BERNSTEIN, P.L.C.  
1950 Roland Clarke Place  
Reston, VA 20191  
(703) 716-1191

Arnold Turk  
Reg. No. 33094

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,709,282

APPLICATION NO.: 10/575,489

ISSUE DATE : May 4, 2010

INVENTOR(S): H. FUKSHIMA, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At column 16, lines 64-65 (claim 1, lines 8-9) of the printed patent, after "wherein said transfer layer", --wherein a thickness of said transfer layer -- should be inserted

At column 17, line 5 (claim 1, line 16) of the printed patent, "wherein a pitch" should read -- wherein a pitch of said minute unevenness structure--

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C.  
1950 Roland Clarke Place  
Reston, VA 20191-1411

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: **Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

*If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.*